



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XFE

Vauxhall Vivaro 2900 1.5d 100PS Edition H1 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	31/12/2019	Colour	WHITE	CAP Average	£7,000.00
Year	2019	VIN	VXEVBVHRKL7007089	CAP Below	£5,450.00
Mileage	47,442 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	18/09/2026	Gears	6
GVW	2830kg	CAP Clean	£8,075.00		

WARNING LIGHT ON DASH AD-BLUE, E/MIRRORS, TWIN SIDE LOAD DOOR

Tyres


NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint



4: Carpets Front
 Holed
 Over 3mm

5: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault