



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XGN

Vauxhall Vivaro 2900 1.5d 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

| | | | | | |
|-----------|---------------------------|------------|--------------------|-------------|-----------|
| Reg. date | 29/01/2020 | Colour | WHITE | CAP Average | £6,425.00 |
| Year | 2020 | VIN | VXEVBVYHRKLZ014612 | CAP Below | £5,125.00 |
| Mileage | 65,776 Miles Warranted | Body Style | Panel Van L1 | Gearbox | MANUAL |
| Fuel Type | Diesel | MOT Due | 29/08/2026 | Gears | 6 |
| GVW | 2830kg | CAP Clean | £7,300.00 | | |

WARNING LIGHTS ON DASH TWIN SIDE LOAD DOOR, E/WMIRRORS, AD-BLUE, DEADLOCKS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Door osr
Dented
Over 30% Of Panel

4: Carpets Front
Holed
Over 3mm



5: Dash Warning Lights
Displayed
No Action

Interior

| Carpet Condition | Poor | Upholstery Condition | OK |
|-----------------------|-------|-------------------------------------|-------|
| Seat Condition | OK | Odour | No |
| Engine Runs | OK | No Excessive Smoking | OK |
| EML light illuminated | Fault | DPF light illuminated | Fault |
| ABS light illuminated | OK | Service indicator light illuminated | Fault |