



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XJW

Vauxhall Vivaro 2900 1.5d 100PS Edition

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	31/12/2019	Colour	WHITE	CAP Average	£5,875.00
Year	2019	VIN	VXEVBVYHRKL7006619	CAP Below	£4,550.00
Mileage	74,016 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	17/03/2027	Gears	6
GVW	2830kg	CAP Clean	£6,800.00		

TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE, DEADLOCKS

Tyres



NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Dented
Over 30mm

4: Qtr Panel osr
Dented
Over 30mm



5: Door osf
Scratched
Over 25mm Thru Paint



6: Wing osf
Dented
With Paint Damage

7: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		