



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XJZ

Vauxhall Vivaro 2900 1.5d 100PS Edition H1 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/12/2019

Year 2019

Mileage 48,006 Miles
Warranted

Fuel Type Diesel

GVW 2830kg

Colour WHITE

VIN VXEVBYHRKL7006081

Body Style Panel Van L1

MOT Due 17/09/2026

CAP Clean £7,900.00

CAP Average £6,825.00

CAP Below £5,300.00

Gearbox MANUAL

Gears 6

AD-BLUE, E/MIRRORS, TWIN SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

Photos






AUTOMOBILES PEUGEOT
 n° 200746-0533
 VXEVBYHRK17006081
 2880 KG
 1- 4230 KG
 2- 1800 KG
 VBYHRK-AZF01D
 2940093



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint



4: Qtr Panel nsr
 Dented
 With Paint Damage

5: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

OK
 OK

Upholstery Condition
Odour

OK
 No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		