



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XAW

Vauxhall Vivaro 2900 1.5d 100PS Edition

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	31/10/2019	Colour	WHITE	CAP Average	£6,650.00
Year	2019	VIN	VXEVBVYHRKL7005055	CAP Below	£5,175.00
Mileage	55,223 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	30/08/2026	Gears	6
GVW	2830kg	CAP Clean	£7,700.00		

TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE, DEADLOCKS (NO KEYS)


Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Over 5mm



3: Qtr Panel nsr
Dented
With Paint Damage

4: Qtr Panel osr
Dented
Over 30mm



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Door Moulding osf
Missing
Replace

8: Wing osf
Scratched
Over 25mm Thru Paint



9: Door Pad osf
Scuffed
Over 25mm

10: Seat Base Cover nsf
Soiled
Heavy



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	Fault