



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XJX

Vauxhall Vivaro 2900 1.5 100PS EDITION

Non Runner

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	29/11/2019	Colour	WHITE	CAP Average	£5,950.00
Year	2019	VIN	VXEVBVYHRKL7005665	CAP Below	£4,625.00
Mileage	Not Showing	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	11/09/2026	Gears	6
GVW	2830kg	CAP Clean	£6,900.00		

NON RUNNER - AD-BLUE MALFUNCTION TWIN SIDE LOAD DOOR, E/MIRRORS, MOT SHOWS 66,458 MILES 10/09/2025

Tyres


NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front Grill
Broken
Replace



3: Number Plate Front
Broken
Replace

4: Wing nsf
Dented
With Paint Damage



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel osr
Dented
With Paint Damage



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint

