

VEHICLE INSPECTION REPORT

KX63OJV

FUSO CANTER 7C15

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	28/02/2014	VIN	TYAFEC71HRDX05585	Axle Combi	4x2
Year	2014	Body Style	Curtainside	Rear Doors	Roller
Mileage	177,710 Km Not Warranted	MOT Due	31/07/2025	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	GREEN	Gearbox	AUTOMATIC		

SURROUND CAMERA SYSTEM

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos



