

VEHICLE INSPECTION REPORT

RE70LCF

Iveco Eurocargo 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	7500kg	Gearbox	AUTOMATIC
Reg. date	09/11/2020	Colour	WHITE	Axle Combi	4x2
Year	2020	VIN	ZCFA875B602702370	Rear Suspension	Steel
Mileage	75,154 Km Warranted	Body Style	Box Van	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column

WARNING LIGHTS ON DASH

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Cruise control
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



2: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint

4: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint



5: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		