

VEHICLE INSPECTION REPORT

RV70DJF

Iveco Eurocargo 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/10/2020

Colour WHITE

Axle Combi 4x2

Year 2020

VIN ZCFA875B202700812

Rear Suspension Steel

Mileage 82,539 Km Warranted

Body Style Box Van

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

GVW 7500kg

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Door osf
Chipped
Multiple Chips

8: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		