

VEHICLE INSPECTION REPORT

RE70LBZ

Iveco Eurocargo 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2020

Colour WHITE

Axle Combi 4x2

Year 2020

VIN ZCFA875B102702373

Rear Suspension Steel

Mileage 63,201 Km Warranted

Body Style Box Van

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

GVW 7500kg

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Digital radio
- Central locking
- Radio/CD
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint




7: Fascia Trim
Damaged
Replace

8: Door Pad nsf
Broken
Replace



9: Seat Base Cover nsf
Soiled
Heavy

10: Seat Back Cover nsf
Soiled
Heavy



11: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		