

VEHICLE INSPECTION REPORT

LN64CHG

MERCEDES-BENZ ATEGO 818

Inspection

Vehicle

VAT

V5 Present

Details

Reg. date	28/10/2014	Body Style	Box Van	Axle Combi	4x2
Year	2014	Service history	Yes	Rear Suspension	Steel
Mileage	227,951 Km Warranted	Service documents	Printout	Rear Doors	Roller
Fuel Type	Diesel	MOT Due	31/10/2025	Tail Lift	Column
Colour	WHITE	Cab Type	CREW CAB		
VIN	WDB9670012L896141	Gearbox	MANUAL		

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Air conditioning

Photos



