



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BJ19KVT

Ford Transit 350 2.0 TDCi 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	23/05/2019	Colour	WHITE	CAP Average	£3,000.00
Year	2019	VIN	WF0XXTTGXKC40007	CAP Below	£2,350.00
Mileage	153,448 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	Expired	Gears	6
GVW	3500kg	CAP Clean	£3,500.00		

SIDE LOAD DOOR, TOW BAR, AD-BLUE.

Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos






FORD	
e 1*2007/48*1100	
WFOXXATGKXK40007	
YHR8	kg
0.50	kg
308 B	kg
07 R	kg
AA F	kg
ES	kg
W(mm)	L(mm)
E 1750	F00



Condition Check



Damage Photos



1: Roof
Dented
With Paint Damage

2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Flasher Side Repeater os
Broken
Replace



5: Door osf
Rusted
Over 5mm




6: Qtr Panel osr
Dented
Over 30mm



7: Tailgate
Dented
With Paint Damage



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
With Paint Damage

10: Door nsf
Dented
With Paint Damage



11: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK