



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**RV70DCU**

## IVECO EUROCARGO 75-160

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	22/10/2020	Colour	WHITE	Gearbox	AUTOMATIC
Year	2020	VIN	ZCFA875B802700748	Axle Combi	4x2
Mileage	Not Showing	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	Expired	Rear Doors	Roller
GVW	7500kg	Cab Type	DAY CAB	Tail Lift	Column

\*TACHO FAULTY\* MOT SHOWS 109,009KM 17/3/2025,


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Moulding nsf Wing  
Scratched (Painted)  
Over 25mm Thru Paint



3: Bumper Front  
Cracked  
Over 25mm

4: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



5: Wing nsf  
Scratched  
Over 25mm Thru Paint

6: Qtr Panel nsr  
Cracked  
Replace



7: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

8: Qtr Panel osr  
Cracked  
Replace



9: Door osf  
Chipped  
Multiple Chips

10: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



11: Switches And Controls  
Broken  
Replace

12: Dash Warning Lights  
Displayed  
No Action

**Interior**

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** OK  
**Odour** -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK		
ABS light illuminated	OK		