

# VEHICLE INSPECTION REPORT

**RV70DHX**

## Iveco Eurocargo 75-160

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

|           |                      |            |                   |                 |           |
|-----------|----------------------|------------|-------------------|-----------------|-----------|
| Reg. date | 09/11/2020           | Colour     | WHITE             | Gearbox         | AUTOMATIC |
| Year      | 2020                 | VIN        | ZCFA875B702700823 | Axle Combi      | 4x2       |
| Mileage   | 121,372 Km Warranted | Body Style | Box Van           | Rear Suspension | Steel     |
| Fuel Type | Diesel               | MOT Due    | Expired           | Rear Doors      | Roller    |
| GVW       | 7500kg               | Cab Type   | DAY CAB           | Tail Lift       | Column    |

### Tyres

|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |



## Features

- Bluetooth connection
- Cruise control
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

## Photos












## Condition Check




## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Bumper Front Moulding  
Missing  
Replace



3: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

4: Door nsf  
Dented  
With Paint Damage



5: Wing nsf  
Scratched  
Over 25mm Thru Paint

6: Door Moulding osf  
Scratched (Painted)  
Over 25mm Thru Paint



7: Door Pad osf  
Broken  
Replace

## Interior

|                       |    |                       |         |
|-----------------------|----|-----------------------|---------|
| Carpet Condition      | OK | Upholstery Condition  | Average |
| Seat Condition        | OK | Odour                 | -       |
| Engine Runs           | OK | No Excessive Smoking  | OK      |
| EML light illuminated | OK | DPF light illuminated | OK      |
| ABS light illuminated | OK |                       |         |