



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FP69YYA

Vauxhall Vivaro 2900 1.5d 100PS EDITION

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	31/12/2019	Colour	WHITE	CAP Average	£6,225.00
Year	2019	VIN	VXEVBVYHRKL7006609	CAP Below	£4,850.00
Mileage	64,730 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	07/09/2026	Gears	6
GVW	2830kg	CAP Clean	£7,225.00		

WARNING LIGHTS ON DASH, SMOKING AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, DEADLOCKS



Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Dented
Over 30mm

4: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



5: Seat Base Cover nsf
Holed
Over 3mm

6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
No

Engine Runs	OK	No Excessive Smoking	Fault
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault