



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**FL69XKC**

## Vauxhall Vivaro 2900 1.5 100PS EDITION

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	31/12/2019	Colour	WHITE	CAP Average	£6,450.00
Year	2019	VIN	VXEVBVYHRKL7007716	CAP Below	£5,000.00
Mileage	59,856 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	04/10/2026	Gears	6
GVW	2830kg	CAP Clean	£7,450.00		

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, DEADLOCKS, RACKING IN REAR

### Tyres



NSF
NSR
OSF
OSR
Spare

### Features


- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Qtr Panel nsr  
Dented  
With Paint Damage



3: Qtr Panel nsr  
Dented  
With Paint Damage

4: Qtr Panel nsr  
Dented  
With Paint Damage



5: Wing osf  
Dented  
Over 30mm

6: Air Vents osf  
Missing  
Replace

**Interior**

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** Poor  
**Odour** No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		