



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL69XFT

Vauxhall Vivaro 2900 1.5 100PS EDITION

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	29/11/2019	Colour	WHITE	CAP Average	£5,950.00
Year	2019	VIN	VXEVBVYHRKL7005651	CAP Below	£4,625.00
Mileage	72,429 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	21/07/2026	Gears	6
GVW	2830kg	CAP Clean	£6,900.00		

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres


NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Sill ns
Dented
Over 30% Of Panel



2: Qtr Panel nsr
Dented
Over 30mm



3: Qtr Panel nsr
Dented
With Paint Damage

4: Qtr Panel osr
Dented
Over 30mm



5: Qtr Panel osr
Dented
Over 30mm

6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Qtr Panel Moulding os
Scuffed (Unpainted)
Up To 100mm



9: Screen Front
Chipped
Over 10mm

10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition Poor
Seat Condition OK

Upholstery Condition OK
Odour No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		