



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**UK10HAR**

## Mercedes-Benz Sprinter 313 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	03/06/2011	GVW	3500kg	MOT Due	24/09/2026
Year	2011	Colour	WHITE	Gearbox	MANUAL
Mileage	202,081 Miles Not Warranted	VIN	WDB9061352N477437	Gears	5
Fuel Type	Diesel	Body Style	Box Van		

\*WARNING LIGHTS ON DASH\*

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

## Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking

## Photos





# Condition Check



## Damage Photos



1: Seat Base Cover of  
Holed  
Over 3mm

2: Dash Warning Lights  
Displayed  
No Action

## Interior

**Carpet Condition** OK  
**Seat Condition** Poor

**Upholstery Condition** OK  
**Odour** No

**Engine Runs** OK **No Excessive Smoking** OK

EML light illuminated

Fault

DPF light illuminated

OK

ABS light illuminated

OK