



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**GK22PWE**

## Iveco Daily 72-180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	29/04/2022	Colour	WHITE	Gearbox	AUTOMATIC
Year	2022	VIN	ZCFC670D00D697999	Axle Combi	4x2
Mileage	113,469 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	Expired	Rear Doors	Roller
GVW	7200kg	Cab Type	DAY CAB	Tail Lift	Column

### Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Park assist camera
- Air conditioning

## Photos





## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



2: Fog Lamp Surround os  
Broken  
Replace



3: Bonnet  
Chipped  
Multiple Chips

4: Bonnet  
Dented  
With Paint Damage



5: Front TowEye Cvr  
Missing  
Replace

6: Bumper Front  
Dented  
Over 30mm



7: Wing nsf  
Dented  
With Paint Damage

8: Panel Front  
Poor Previous Repair  
Poor Colour



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

10: Bumper Rear  
Rusted  
Over 5mm



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

12: Seat Base Cover osf  
Missing  
Replace



13: Seat Base Cover osf  
Burn  
Over 3mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK