

VEHICLE INSPECTION REPORT

SK11HBJ

MAN TGS 26.320

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | Present |

Details

| | | | | | |
|-----------|----------------------|------------|-------------------|-----------------|-----------|
| Reg. date | 07/03/2011 | Colour | WHITE | Gearbox | AUTOMATIC |
| Year | 2011 | VIN | WMA18SZZ9AW137109 | Axle Combi | 6x2 |
| Mileage | 507,106 Km Warranted | Body Style | Flatbed | Rear Suspension | Air |
| Fuel Type | Diesel | Keys | 2 | | |

SURROUND CAMERA SYSTEM, TWIST LOCKS (6) *WARNING LIGHTS ON DASH*

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos



