



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**SD22DJE**

## Renault Master LM35 2.3 dCi 135PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details			
Reg. date	30/03/2022	Colour	WHITE
Year	2022	VIN	VF1MA000768689946
Mileage	87,322 Miles Not Warranted	Body Style	Panel Van LWB
Fuel Type	Diesel	MOT Due	Expired
GVW	3500kg	CAP Clean	£9,450.00
		CAP Average	£8,625.00
		CAP Below	£7,250.00
		Gearbox	MANUAL
		Gears	6

\*REAR DOOR INOPERABLE\* \*WINDSCREEN CRACKED\* SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

## Features


- Radio/CD
- Front electric windows
- Central locking

## Photos





# Condition Check



## Damage Photos



1: Door osf  
Chipped  
Edge Chip

2: Door osf  
Rusted  
Over 5mm



3: Wing osf  
Dented  
With Paint Damage

4: Screen Front  
Chipped  
UpTo 10mm



5: Bumper Front Moulding  
Broken  
Replace

6: Bumper Front Moulding  
Broken  
Replace



7: Wing nsf  
Dented  
With Paint Damage

8: Door nsf  
Dented  
With Paint Damage



9: Qtr Panel Moulding ns  
Missing  
Replace

10: Door nsr  
Dented  
With Paint Damage



11: Qtr Panel nsr  
Dented  
With Paint Damage

12: Aperture Seal nsr  
Missing  
Replace



13: Bumper Rear  
Cracked  
Over 25mm

14: Door Moulding osr  
Missing  
Replace



15: Handle Outer osr  
Missing  
Replace



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Aperture Seal osr  
Missing  
Replace



18: Qtr Panel osr  
Dented  
With Paint Damage



19: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



20: Qtr Panel osr  
Dented  
With Paint Damage

## Interior

<b>Carpet Condition</b>	Poor	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor	<b>Odour</b>	Yes
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	Fault	Steering	OK