

VEHICLE INSPECTION REPORT

PO68JZW

Fiat Ducato 35 2.3 Multijet 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/10/2018

Year 2018

Mileage 160,214 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002H90742

Body Style Panel Van MWB

MOT Due 07/10/2025

CAP Clean £3,150.00

CAP Average £2,725.00

CAP Below £2,125.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, E/ MIRRORS, POWER INVERTER

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Dented
With Paint Damage



3: Qtr Panel Moulding ns
Broken
Replace



4: Door Pad osf
Soiled
Heavy



5: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	OK		Odour	-
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			