



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LJ73EEA

Fisker Ocean One 421kW Extreme 113kWh Hyper Range AWD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

Details					
Reg. date	27/10/2023	Colour	BLACK	CAP Below	£10,250.00
Year	2023	VIN		Gearbox	AUTOMATIC
Mileage	7,868 Miles Not Warranted	Body Style	SUV	Gears	1
Fuel Type	ELECTRIC	CAP Clean	£12,750.00		
GVW	2974kg	CAP Average	£11,500.00		

KEYLESS IGNITION




Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Air conditioning
- Passenger airbag
- Cruise control
- Park assist camera
- Reverse parking aid
- Climate control
- Central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Metallic Paint
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Drivers airbag
- Alloy wheels


Photos







Condition Check



Damage Photos



1: Wheel nsf
Scratched
Over 50mm



2: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



3: A Post ns
Dented
Over 30mm

4: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No