



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

AV22VRY

Daf XF 530

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	24/05/2022	Colour	WHITE
Year	2022	VIN	XLRTGF5300G407593
Mileage	406,474 Km TBC	Body Style	Tractor Unit
Fuel Type	Diesel	Cab Type	HIGH ROOF SLEEPER CAB
GVW	44000kg	Gearbox	AUTOMATIC
		Axle Combi	6x2
		Steering Combi	Mid-Lift Steer
		Rear Suspension	Air

MIRROR CAMS, SLIDING 5TH WHEEL


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint


4: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel Trim ns
Scuffed
Over 25mm

8: Qtr Panel Trim ns
Scuffed
Over 25mm



9: Panel Rear
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Door osf
Scratched
Over 25mm Thru Paint



13: Screen Front
Chipped
Over 10mm

14: Door Pad osf
Soiled
Heavy



15: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		