

# VEHICLE INSPECTION REPORT

**LF19SZD**

## Peugeot Partner 650 1.6 BlueHdi 75 Professional

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 29/03/2019

VIN VR3EFBHWBKJ599710

CAP Below £2,750.00

Year 2019

Body Style Panel Van L1

Gearbox MANUAL

Mileage 99,503 Miles  
Warranted

MOT Due 28/03/2026

Gears 5

Fuel Type Diesel

CAP Clean £3,950.00

Colour WHITE

CAP Average £3,450.00

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Unclassified  
Substantial Accident Damage  
Report Only




3: Qtr Panel osr  
Dented  
Over 30mm



4: Qtr Panel osr  
Dented  
Over 30mm



5: Seat Base Cover osf  
Soiled  
Heavy



6: Seat Base Cover nsf  
Soiled  
Heavy



7: Screen Front  
Chipped  
Over 10mm

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		