



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK74BWM

Volkswagen Amarok 2.0 TDI 205PS STYLE 4MOTION

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	30/09/2024	Colour	BLACK	CAP Average	£28,650.00
Year	2024	VIN	WV4ZZZT13RS011591	CAP Below	£25,200.00
Mileage	17,227 Miles Warranted	Body Style	Pickup Double Cab	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	29/09/2027	Gears	1
GVW	3280kg	CAP Clean	£30,400.00	Axle Combi	4x4

WARNING LIGHT ON DASH ELECTRIC ROLLER, REAR VIEW CAMERA, SPARE WHEEL, HEATED WINDSCREEN, E/MIRRORS, AD-BLUE, LEATHER.

Tyres



NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Heated front seat
- Navigation system
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip

2: Door osf
Scratched
Over 25mm Thru Paint



3: Wing osf
Scratched
Over 25mm Thru Paint

4: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



5: Bonnet
Scratched
Over 25mm Thru Paint

6: Bonnet
Scratched
Over 25mm Thru Paint



7: Bonnet
Scratched
Over 25mm Thru Paint

8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
 Scratched
 Over 25mm Thru Paint

10: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



11: Door Moulding osr
 Scratched (Painted)
 Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		