



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**WU67YHN**

## Fiat Ducato 35 2.0 MULTIJET 115PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 21/09/2017

Year 2017

Mileage 104,802 Miles  
Warranted

Fuel Type Diesel

GVW 3500kg

Colour WHITE

VIN ZFA25000002F09105

Body Style Panel Van MWB

Service history Yes

MOT Due 09/10/2026

CAP Clean £4,025.00

CAP Average £3,350.00

CAP Below £2,475.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, E/ MIRRORS, DEADLOCKS, WATER HEATER, 230V OUTLETS

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features


- Bluetooth connection
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Number Plate Front  
Broken  
Replace



3: Bumper Front  
Scratched  
Over 100mm Thru Paint

4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

6: Qtr Panel nsr  
Dented  
Over 30mm



7: Door nsr  
Scratched  
Over 25mm Thru Paint

8: Door nsr  
Dented  
With Paint Damage



9: Door nsr  
Chipped  
Multiple Chips

10: Door osr  
Chipped  
Multiple Chips



11: Screen Front  
Chipped  
Over 10mm

12: Door Pad osf  
Soiled  
Heavy

**Interior**

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** Poor  
**Odour** No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		