



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GK71TSY

Iveco Daily 72-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	08/12/2021	VIN	ZCFC670D70D692587	Axle Combi	4x2
Year	2021	Body Style	Box Van	Rear Suspension	Steel
Mileage	163,155 Km Warranted	MOT Due	28/02/2027	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

COLLECTED AS NON - RUNNER, HALF SHAFT NOT SECURE, BOLTS IN DOOR PANEL, WARNING LIGHTS ON DASH

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Digital radio
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Scratched
Up To 25mm Not Thru Paint

6: Panel Rear
Dented
With Paint Damage



7: Panel Rear
Dented
With Paint Damage

8: Panel Front
Dented
With Paint Damage



9: Seat Base Cover of
 Holed
 Over 3mm

10: Bumper Front Moulding
 Missing
 Replace

Interior

Carpet Condition
Seat Condition

Average
 Poor

Upholstery Condition
Odour

Average
 -

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK