



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GK71TTF

Iveco Daily 72-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	08/12/2021	Colour	WHITE	Gearbox	AUTOMATIC
Year	2021	VIN	ZCFC670D70D692590	Axle Combi	4x2
Mileage	188,897 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	28/02/2027	Rear Doors	Roller
GVW	7200kg	Cab Type	DAY CAB	Tail Lift	Cantilever

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Door osf
Dented
With Paint Damage

2: Door osf
Chipped
Edge Chip



3: Panel Rear
Hole
Over 10mm

4: Panel Rear
Hole
Over 10mm



5: Door nsf
Chipped
Edge Chip

6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Wing nsf
Dented
Over 30mm

8: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



9: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

10: Seat Base Cover of
Torn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK