

VEHICLE INSPECTION REPORT

PN68BVG

Renault D 18

Cat: N
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	15/10/2018	VIN	VF620J868KB005793	Axle Combi	4x2
Year	2018	Body Style	Curtainside	Rear Suspension	Air
Mileage	287,105 Km Not Warranted	MOT Due	31/12/2025	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	HIGH ROOF SLEEPER CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		

WARNING LIGHT ON DASH Category N Insurance Loss,

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Cloth seat trim
- Digital radio
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Broken
Replace

4: Bumper Front Moulding
Broken
Replace



5: Qtr Panel osr
Hole
Over 10mm

6: Seat Base Cover osf
Torn
Over 3mm



7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		