



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK61YNW

Mercedes-Benz Axor 1843

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 26/10/2011

Year 2011

Mileage 1,586,785 Km Not Warranted

Fuel Type Diesel

GVW 28000kg

Colour WHITE

VIN WDF9440322B974528

Body Style Tractor Unit

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osf
Scratched
Over 25mm Thru Paint

4: Panel Rear
Rusted
Over 5mm



5: Moulding osf Wing
Scuffed (Unpainted)
Over 100mm

6: Panel Rear
Rusted
Over 5mm



7: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm

8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
-

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK