

VEHICLE INSPECTION REPORT

C338841

DON-BUR BOX DOUBLE DECK

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | N/A |

Details

| | | | | | |
|-----------|------|-------------------|----------|-----------------|--------|
| Reg. date | | VIN | | Axle Combi | Tri |
| Year | 2013 | Body Style | Trailer | Rear Suspension | Air |
| Mileage | TBC | Service history | Yes | Rear Doors | Roller |
| Fuel Type | | Service documents | Printout | | |
| Colour | RED | Brakes | Disc | | |

WIRING FAULT BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



