

# VEHICLE INSPECTION REPORT

**PO13DGU**

## Daf LF 45.140

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	01/03/2013	VIN	XLRAE45FF0L424204	Cab Type	DAY CAB
Year	2013	Body Style	Box Van	Gearbox	MANUAL
Mileage	974,214 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/03/2026	Tail Lift	Cantilever

\*COLLECTED AS NON RUNNER - CAB ROT, TAIL LIFT, TYRE ISSUES\*


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

### Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front Grill  
Broken  
Replace



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Door osf  
Dented  
Over 30mm



5: Door osf  
Scratched  
Over 25mm Thru Paint



6: Door Pad osf  
Soiled  
Heavy



7: Carpets Front  
Torn  
Over 10mm



8: Seat Base Cover nsf  
Holed  
Over 3mm





9: Door Pad nsf  
Soiled  
Heavy



10: Screen Front  
Chipped  
Over 10mm

**Interior**

<b>Carpet Condition</b>	Poor		<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor		<b>Odour</b>	-
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			