



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**WX65GJV**

## Ford Ranger XL 2.2 TDCI 150PS

**Non Runner**

### Inspection

Serious Damage? No

### Vehicle

VAT	Plus VAT
V5	Buyer To Apply

### Details

Reg. date	23/11/2015	Colour	WHITE	CAP Average	£4,000.00
Year	2015	VIN	6FPGXXMJ2GFY86508	CAP Below	£2,800.00
Mileage	76,627 Miles Warranted	Body Style	Pickup Single Cab	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	Expired	Gears	6
GVW	3200kg	CAP Clean	£4,975.00	Axle Combi	4x4

\*NON-RUNNER - NO ENGINE, DAMAGE TO BODY\* TOW BAR, E/ MIRRORS, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

### Tyres


NSF
NSR
OSF
OSR
Spare

## Features


- Radio/CD
- Passenger airbag
- Air conditioning
- Cloth seat trim
- Front electric windows
- Drivers airbag

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint

2: Bonnet  
Dented  
Over 30mm



3: Bonnet  
Dented  
Over 30mm

4: Bonnet  
Scratched  
Over 25mm Thru Paint



5: Wing nsf  
Dented  
Hail - Severe

6: Door Mirror Assy nsf  
Broken  
Replace



7: Door nsf  
Dented  
Over 30% Of Panel

8: Handle Outer nsf  
Broken  
Replace




9: Qtr Panel nsr  
Dented  
Over 30% Of Panel

10: Sill ns  
Dented  
Over 30mm



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

12: Qtr Panel nsr  
Dented  
With Paint Damage



13: Lamp nsr  
Broken  
Replace

14: Bumper Rear  
Dented  
Over 30mm



15: Qtr Panel osr  
Dented  
With Paint Damage

16: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



17: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

18: Door osf  
Chipped  
Multiple Chips



19: Wing osf  
Dented  
Over 30mm

20: Bumper Front Moulding  
Missing  
Replace



21: Bumper Front  
Scratched  
Over 100mm Thru Paint

22: Centre Console Front  
Holed  
Over 3mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** -

**Engine Runs** Fault