



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**BL64UUO**

## Mercedes-Benz Actros 1840

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	23/01/2015	Colour	WHITE	Gearbox	AUTOMATIC
Year	2015	VIN	WDB9634032L922170	Axle Combi	4x2
Mileage	908,869 Km Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	31/10/2026		
GVW	28000kg	Cab Type	CLASSICSPACE CAB		

### SURROUND CAMERA SYSTEM

### Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Air conditioning

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Not Thru Paint

2: Screen Front  
Chipped  
Over 10mm



3: Qtr Panel nsr  
Cracked  
Replace

4: Qtr Panel osr  
Cracked  
Replace



5: Door osf  
Chipped  
Edge Chip

6: Wing Front Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



7: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK