



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**LT18XRW**

## Toyota Hilux 2.4 D-4D

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	10/05/2018	Colour	WHITE	CAP Average	£6,825.00
Year	2018	VIN	AHTHB3CD502126472	CAP Below	£5,175.00
Mileage	156,074 Miles Warranted	Body Style	Pickup Double Cab	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	09/05/2027	Gears	6
GVW	3210kg	CAP Clean	£8,025.00		

### E/MIRRORS

### Tyres

NSF

NSR

OSF


OSR



Spare

## Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking
- Auxiliary input socket
- Rear electric windows
- Cloth seat trim

## Photos










## Condition Check



## Damage Photos



1: Carpets Front  
Soiled  
Heavy




2: General Interior  
Soiled  
Light




3: Seat Base Cover nsf  
Soiled  
Light

4: Bumper Front  
Poor Previous Repair  
Paint Flake



5: Sill os  
Scratched  
Over 25mm Thru Paint

6: Roof  
Rusted  
Over 5mm



7: Door osf  
Chipped  
Edge Chip

8: Door osf  
Chipped  
Over 5mm



9: Tailgate  
 Scratched  
 Over 25mm Thru Paint

10: Panel Front  
 Dented  
 With Paint Damage



11: Door nsf  
 Scratched  
 Over 25mm Not Thru Paint

12: Wing nsf  
 Chipped  
 Over 5mm

**Interior**

<b>Carpet Condition</b>	Poor	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor	<b>Odour</b>	Yes
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK