



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**LM20DBV**

## Toyota Hilux 2.4 D-4D TSS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 17/07/2020

Year 2020

Mileage 125,397 Miles  
Warranted

Fuel Type Diesel

GVW 3210kg

Colour WHITE

VIN AHTKB3CD602630857

Body Style Pickup Double Cab

MOT Due 16/07/2026

CAP Clean £9,425.00

CAP Average £8,275.00

CAP Below £6,625.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

TOW BAR, E/MIRRORS

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

## Photos






TOYOTA SAZOO Racing Europe GmbH  
 a13\*2007/46\*1698  
 STAGE 2  
 AHTKB3CD602630857

|    |      |    |
|----|------|----|
| 1- | 3210 | kg |
| 2- | 5650 | kg |
|    | 1920 | kg |

MODEL: GUN125R-DNFSW M


TOYOTA MOTOR EUROPE NV / SA  
 K5 2007/46 0337  
 X-ITKB3CD602630857

4118 0410 / FG90  
 4118 0018 / PG90F





## Condition Check



## Damage Photos



1: Sill os  
Dented  
Over 2 UpTo 10mm



2: Qtr Panel osr  
Dented  
With Paint Damage



3: Panel Rear  
 Scratched  
 Rusted

**Interior**

| <b>Carpet Condition</b>  | OK | <b>Upholstery Condition</b>                    | OK |
|--------------------------|----|--|----|
| <b>Seat Condition</b>    | OK | <b>Odour</b>                                   | No |
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio  | OK |
|                          |    | Steering                                       | OK |