



COMMERCIAL VEHICLE AUCTIONS LTD  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**GK22PVL**

## Iveco Daily 72-180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 28/04/2022

GVW 7200kg

Gearbox AUTOMATIC

Year 2022

Colour WHITE

Tail Lift Column

Mileage 141,238 Km Warranted

VIN ZCFC670D90D697984

Fuel Type Diesel

Body Style Box Van

REAR VIEW CAMERA.

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features


- Radio/CD
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover of  
Torn  
Over 3mm



2: Bonnet  
Dented  
With Paint Damage



3: Wing osf  
Dented  
With Paint Damage

4: Qtr Panel osr  
Rusted  
Over 5mm



5: Tailgate  
Rusted  
Over 5mm

6: Qtr Panel nsr  
Rusted  
Over 5mm



7: Door nsf  
Dented  
With Paint Damage

8: Wing nsf  
Dented  
With Paint Damage

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK