

VEHICLE INSPECTION REPORT

NX69NWA

Renault T 520

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 10/09/2019

Year 2019

Mileage 707,521 Km Not Warranted

Fuel Type Diesel

GVW 44000kg

Colour WHITE

VIN VF611C365KD001734

Body Style Tractor Unit

MOT Due 30/09/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHT ON DASH SLIDING 5TH WHEEL

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Leather seat trim
- Air conditioning


Photos








Condition Check



Damage Photos



1: Fascia Trim
Missing
Replace

2: Fascia Trim
Missing
Replace



3: Dash Warning Lights
Displayed
No Action

4: Bonnet
Chipped
Multiple Chips



5: Number Plate Front
Missing
Replace

6: Bonnet
Scratched
Over 25mm Thru Paint



7: Bumper Front
Scratched
Over 100mm Thru Paint

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Handle Outer nsf
Scratched (Painted)
Over 25mm Thru Paint

10: Wing Front Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel nsr
Cracked
Replace



13: Door osf
Chipped
Multiple Chips

14: Wing osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

16: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			