



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
 Doncaster
 DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GK22PRX

IVECO DAILY 70C18

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	04/05/2022	Colour	WHITE	Gearbox	AUTOMATIC
Year	2022	VIN	ZCFC670D70D697997	Axle Combi	4x2
Mileage	183,073 Km Warranted	Body Style	Luton L3	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	Expired	Rear Doors	Roller
GVW	7200kg	Cab Type	DAY CAB	Tail Lift	Column

UNEVEN IDLE-SMOKES EXCESSIVELY, RADIO REQUIRES CODE - NO CODE SUPPLIED.


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning

Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
Up To 25mm Thru Paint

6: Qtr Panel nsr
Hole
Over 10mm



7: Door osf
Chipped
Multiple Chips

8: Door osf
Scratched
Over 25mm Thru Paint



9: Door Mirror Assy of
Broken
Replace

10: Bonnet
Scratched
Over 25mm Thru Paint



11: Wing of
Chipped
1 To 5

12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Sunvisor ns
Missing
Replace

14: Centre Console Front
Holed
Over 3mm



15: Fascia Trim
 Missing
 Replace

Interior

Carpet Condition	Average	Upholstery Condition	-
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		