

VEHICLE INSPECTION REPORT

YF74EE0

Iveco Daily 72-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 04/12/2024

Year 2024

Mileage 98,223 Km Warranted

Fuel Type Diesel

GVW 7200kg

Colour WHITE

VIN ZCFCE72C50D777743

Body Style Dropside

MOT Due 31/12/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHTS ON DASH


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check




Damage Photos



1: Panel Front
Scratched
UpTo 25mm Thru Paint

2: Door Mirror Assy nsf
Broken
Replace



3: Screen Front
Chipped
Over 10mm

4: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault