

VEHICLE INSPECTION REPORT

RV70DFC

Iveco Eurocargo 75-160

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	22/10/2020	Colour	WHITE	Gearbox	AUTOMATIC
Year	2020	VIN	ZCFA875B302700740	Axle Combi	4x2
Mileage	123,925 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/12/2026	Rear Doors	Roller
GVW	7500kg	Cab Type	DAY CAB	Tail Lift	Column


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm

2: Front TowEye Cvr
Missing
Replace



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

8: Door osf
Scratched
Over 25mm Thru Paint



9: Door osf
 Chipped
 Edge Chip

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK