

VEHICLE INSPECTION REPORT

C320401

DENNISON CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster	Fuel Type		Brakes	Drum
Reg. date	01/01/2011	Colour	GREEN	Axle Combi	Tri
Year	2011	VIN	26395	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn

BPW AXLES, RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



