

# VEHICLE INSPECTION REPORT

**C499029**

## SDC CURTAINSIDE

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |      |            |                   |                 |      |
|-----------|------|------------|-------------------|-----------------|------|
| Reg. date |      | Colour     | BLUE              | Brakes          | Disc |
| Year      | 2019 | VIN        | SDCCS45B300177107 | Axle Combi      | Tri  |
| Mileage   | TBC  | Body Style | Trailer           | Rear Suspension | Air  |
| Fuel Type |      | MOT Due    | 31/03/2026        | Rear Doors      | Barn |

BPW AXLES, RAISE & LOWER VALVE, ENXL RATED

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos



