

# VEHICLE INSPECTION REPORT

**MA56287**

## KRONE CURTAINSIDE MEGA EUROLINER

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |             |            |                   |                 |      |
|-----------|-------------|------------|-------------------|-----------------|------|
| Reg. date | 01/01/2015  | Colour     | BLUE              | Axle Combi      | Tri  |
| Year      | 2015        | VIN        | WKESD000000682208 | Rear Suspension | Air  |
| Mileage   | Not Showing | Body Style | Trailer           | Rear Doors      | Barn |
| Fuel Type |             | Brakes     | Drum              |                 |      |

\*NOT REGISTERED IN THE UK, BRAKES STUCK ON, AIR TANK REQUIRES REPLACING\* BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS, SLIDING ROOF, ENXL RATED

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos







