

VEHICLE INSPECTION REPORT

MK25XNB

Daf XBC 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	25/03/2025	Colour	WHITE/BLUE	Gearbox	AUTOMATIC
Year	2025	VIN	XLRAEL3700L544100	Axle Combi	4x2
Mileage	19,904 Km Warranted	Body Style	Skiploader	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/07/2027		
GVW	18000kg	Cab Type	DAY CAB		

WARNING LIGHTS ON DASH BOUGHTON PR18 BODY, SHEETING SYSTEM

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Door osf
Scratched
Over 25mm Thru Paint



3: Seat Back Cover osf
Soiled
Heavy

4: Seat Base Cover nsf
Soiled
Heavy



5: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		