

VEHICLE INSPECTION REPORT

HT19W XK

Citroen Relay 30 2.0 BlueHDI Enterprise

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	28/06/2019	Colour	WHITE	CAP Average	£4,725.00
Year	2019	VIN	VF7YA1MFA12L23906	CAP Below	£3,675.00
Mileage	138,862 Miles Not Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	Expired	Gears	6
GVW	3000kg	CAP Clean	£5,475.00	Axle Combi	4x2

WARNING LIGHT ON DASH AD BLUE, SIDE LOAD DOOR, ROOF RACK, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Radio/CD
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Rear parking sensor
- Front electric windows
- Mobile phone App interface
- Drivers airbag

Photos





Condition Check




Damage Photos



1: Screen Front
Chipped
Over 10mm

2: Wing nsf
Dented
With Paint Damage




3: Wing nsf
Dented
Over 30mm

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Door osr
Dented
Between 10mm + 30mm

8: Door osr
Dented
Over 2 UpTo 10mm



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel osr
Dented
Over 30mm



11: Sill os
Dented
Over 30mm

12: Door Qtr Light nsf
Missing
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			