

VEHICLE INSPECTION REPORT

NX21UPA

Man TGX 18.640

Non Runner
Inspection

Vehicle	
Serious Damage?	No
VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	10/03/2021	GVW	34000kg	Cab Type	GX CAB
Year	2021	Colour	BLUE	Gearbox	AUTOMATIC
Mileage	TBC	VIN	WMA06KZZXMM881884	Axle Combi	4x2
Fuel Type	Diesel	Body Style	Tractor Unit	Rear Suspension	Air

NON-RUNNER - STARTS AND DRIVES, FRONT WHEELS INSECURE, WARNING LIGHTS ON DASH




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Metallic Paint
- Central locking
- Leather seat trim


Photos







Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

4: Bumper Front Moulding
Broken
Replace



5: Door Moulding of
Scratched (Painted)
Over 25mm Thru Paint

6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	Fault