

VEHICLE INSPECTION REPORT

SD17FYV

Renault Master LL35 2.3dCi 130PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/04/2017

Year 2017

Mileage 78,022 Miles
Warranted

Fuel Type Diesel

GVW 3500kg

Colour BLUE

VIN VF1MB000557475006

Body Style Dropside Double Cab

MOT Due 07/06/2027

CAP Clean £6,050.00

CAP Average £5,050.00

CAP Below £3,750.00

Gearbox MANUAL

Gears 6

TOW BAR,.

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check




Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
Over 30mm

4: Door osf
Dented
With Paint Damage



5: Door osr
Dented
Over 30mm

6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Door nsr
Dented
With Paint Damage



9: Door nsf
Dented
With Paint Damage

10: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average		Average	
Average		No	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK