

VEHICLE INSPECTION REPORT

CL23EKX

Peugeot Expert 1000 1.5 BlueHDi 100 Professional Premium +

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/07/2023

VIN VF3VBYHRMP7837774

CAP Below £10,300.00

Year 2023

Body Style Panel Van L1

Gearbox MANUAL

Mileage 20,580 Miles Not Warranted

MOT Due 30/07/2026

Gears 6

Fuel Type Diesel

CAP Clean £12,500.00

Colour WHITE

CAP Average £11,750.00

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- USB/iPod interface
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Wing nsf
Dented
With Paint Damage



3: Qtr Panel osr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Dented
Over 30mm



5: Qtr Panel osr
Dented
With Paint Damage



6: Seat Base Cover nsf
Soiled
Heavy



7: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		